AXAF COMMAND ACTION PROCEDURE

CAP #: 540
DATE: 4 Jan 2000

ORIGINATOR: Paul Plucinsky
COMMANDS CHECKED BY:
Time of CAP Execution (GMT): 008:18:30 OR 009:0

DESCRIPTION/RATIONALE

Load the new Standard and Optional Patches Rev B and re-start DEA Housekeeping.

RESTRICTIONS/WARNINGS/NOTES/SCHEDULE REQT:

FMT 2 needed. This commanding will be interleaved upon the daily load. There should be no potential conflicts except with ACIS, but the operators should be cognizant nevertheless.

STEP	INSTRUCTIONS (Command/Script)	RESPONSE (TLM Verifier)
	EXECUTE:	
1	SOP_61083_SW_EVHCC3X3B	ACIS verifies
2	SOP_61010_DEA_HKP	ACIS verifies

Approved:

Subsystem Engineer:
TST Manager/Lead:
SOT Lead:

Flight Director:
Program Manager: