AXAF COMMAND ACTION PROCEDURE

CAP # 626 Rev B	ORIGINATOR: Paul Plucinsky
DATE: 29 June 2000	COMMANDS CHECKED BY:
	Time of CAP Execution (GMT): 181:00:58

DESCRIPTION/RATIONALE

This CAP is the **AS-RUN** version of CAP 626. See CAP 626 Rev A for the intention of the CAP. Due to problems with the Squirt connection to the EGSE and the poor COM on Madrid, CAP 626 had to be truncated. See SOT shift report Jun_28_2000_H342.txt for additional details.

The plan is:

- Power down the FEPs, WSFEPALLDN
- Dump Flight SW
- execute normal CTI I array (rerun of CAP 574)

RESTRICTIONS/WARNINGS/NOTES/SCHEDULE REQT:

STEP	INSTRUCTIONS (Command/Script)	RESPONSE (TLM Verifier)
	EXECUTE:	
1	Uplink Load 180:22:30	
	1A_RB000_196.CLD	40E372D
2	switch to DSS 24 181:00:50	
3	Uplink Load 181:01:05	
	1A_WS003_165.CLD	8121972
4	Enable and Activate SCS 165 181:01:06	WSFEPALLDN (cmdId = 1542)
5	clear and disable SCS 165 181:01:07	
6	Uplink Load 181:01:09	
	1A_CTI00_137.CLD 181:01:10	E1940CB
7	Enable and Activate SCS 137 181:01:10	WSVIDALLDN (command ID = 1541)
		WSPOW0CF3F (command ID = 359)
		RS_0000001 (command ID = 66)
		RH_0000001 (command ID = 68)
		WT00216014 (command ID = 2034)
8	ACIS confirms	XTZ0000005 (command ID = 58)
9	Enable and Activate SCS 196 181:01:17	RBROMDUMP1 (cmdId = 306)
10	Disable and clear SCS 196 181:01:25	
11	Clear and Disable 137 181:01:39	
12	LOS on DSS 24 181:01:46	

Approved:

Subsystem Engineer:
TST Manager/Lead:
SOT Lead:

Flight Director:
Program Manager: