AXAF COMMAND ACTION PROCEDURE

CAP #: 917
DATE: 26 May 2004

ORIGINATOR: Royce E. Buehler
COMMANDS CHECKED BY:
Time of CAP Execution (GMT): 2004:155::14:10

DESCRIPTION/RATIONALE

Load the Standard Rev B Patches, Optional Patches Rev C and re-start DEA Housekeeping.

RESTRICTIONS/WARNINGS/NOTES/SCHEDULE REQT:

FMT 2 needed. This commanding will be interleaved upon the daily load. There should be no potential conflicts except with ACIS, but the operators should be cognizant nevertheless. We will wait until the end of the descending leg CTI measurement before executing the CAP.

STEP	INSTRUCTIONS (Command/Script)	RESPONSE (TLM Verifier)
	EXECUTE:	
1	SOP_ACIS_SW_EVHCC3X3_CATL	ACIS verifies
2	SOP_61010_DEA_HKP	ACIS verifies

Approved:

Subsystem Engineer:
TST Manager/Lead:
SOT Lead:

Flight Director:
Program Manager: